




1/10



BEST AVAILABLE COPY


FIG. 1



Needle Free Medical Connector With Expanded Valve Mechanism . . .

Inventor(s): Leinsing et al.  
Application No.: 09/998,383  
Docket No.: 56075

FIG. 2



3/10




FIG. 3




FIG. 4



4/10

FIG. 5






FIG. 6







6/10





FIG. 8

FIG. 9






FIG. 10

8/10

FIG. 11





FIG. 12

9/10

FIG. 13





FIG. 14

FIG. 15

Needle Free Medical Connector With Expanded Valve Mechanism . . .

Inventor(s): Leinsing et al.  
Application No.: 09/998,383  
Docket No.: 56075



10/10




FIG. 16




FIG. 17




FIG. 18

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**